



KUSTOM SIGNALS, INC.

## Service Bulletin

**Number:** 1559  
**Date Issued:** March 6, 2007  
**Product Affected:** Digital Eyewitness NXT, ION, PC DEMM, Workstation DEMM & Server DEMM  
**Reason For Bulletin:** Daylight Saving change to March and November dates.

### ***Problem:***

The new daylight savings time change enacted for 2007 is different than it has been for the past years. All systems manufactured have pre-2007 April and October dates.

### ***Solution:***

The operating systems require an update from Microsoft. Install the patches provided by Microsoft for PC DEMM, Workstation DEMM and Server DEMM. For the NXT and ION, a registry patch has been created that can be installed via the removable media.

### **Corrective Procedure NXT/ION**

1. A repair zip file named [014-1044-00v1\\_0.zip](#) exists to correct this issue. The zip file contains all the necessary files and a PDF of the instructions. Click the link to download the file, or go to [www.kustomsignals.com/downloads/014-1044-00v1\\_0.zip](http://www.kustomsignals.com/downloads/014-1044-00v1_0.zip).
2. Extract the 014-1044-00v1\_0.zip file into a folder of your choice.
3. Read and follow the instructions contained within the 006-0879-00 procedure.

### **Corrective Procedure DEMM Systems**

1. A repair zip file named [014-1045-00v1\\_0.zip](#) exists to correct this issue. The zip file contains all the necessary files and a PDF of the instructions. Click the link to download the file, or go to [www.kustomsignals.com/downloads/014-1045-00v1\\_0.zip](http://www.kustomsignals.com/downloads/014-1045-00v1_0.zip)
2. Extract the 014-1045-00v1\_0.zip file into a folder of your choice. We recommend "Daylight Saving Time".
3. Read and follow the instructions contained within the 006-0883-00 procedure found in the folder created in step 2.

If you need assistance with this installation contact Customer Service at (800) 835-0156.